

Intersil Corporation

intersil

P.O. Box 343
3720 AH Bilthoven
The Netherlands
Rembrandtlaan 1a
3723 BG Bilthoven
The Netherlands

telephone +31 (0)30 229 60 60
facsimile +31 (0)30 229 60 61

Date: 01 May 2003

Our reference
2002-mansup-525-5

Subject: Permission for Actiontec to use Intersil
Documentation

To:
Bay Area Compliance Lab. Corp.
TCB dept.
230 Commercial Street, Sunnyvale,
CA 94086, USA
Phone: 408-732-9162
Fax: 408-732-9164

Dear TCB,

Intersil Corp. hereby grants permission to:

Company	Actiontec Electronics, Inc.
Address, City	760 North Mary Ave.,
Country	Sunnyvale, CA 94086 USA
Phone number	408-752-7700
Fax number	408-732-0087

to use Intersil model: **ISL38000C (FCC ID: OSZ38000C)** documentation for FCC, ETSI and other regulatory certification purposes for the following product:

FCC ID	LNQ802CIG
Brand	Actiontec
Model number	802CIG
Description	IEEE 802.11g WLAN Cardbus Card

This permission is only valid for using the documentation for the above mentioned Intersil model **ISL38000C (FCC ID: OSZ38000C)** and expires on November 1st, 2003.

Yours sincerely,



Derick Sariredjo (derick.sariredjo@intersil.com)
Manufacturing Support / Regulatory Office

Intersil Corp. The Netherlands (www.intersil.com)
Rembrandtlaan 1a
3723 BG Bilthoven, The Netherlands
Phone: +31.30.225.9742
Mobile: +31.62.732.8048
Fax: +31.30.229.6061

www.intersil.com
ING Bank: 65.02.63.049
Swift code: INGBNL2A
VAT / BRW: NL8039.66.659.B.01
Chamber of Commerce Utrecht: 30139807