

**IEEE 802.11ac VHT80 Mode / 5250 ~ 5350MHz (chain 2)
5530MHz**



Date: 30.JUL.2019 15:26:59

5610MHz



Date: 30.JUL.2019 15:28:23

5690MHz



Date: 30.JUL.2019 15:57:50

IEEE 802.11ac VHT80 Mode / 5250 ~ 5350MHz (chain 3) 5530MHz



Date: 30.JUL.2019 15:26:46

5610MHz




Date: 30 JUL 2019 15:28:37

5690MHz




Date: 30 JUL 2019 15:59:18

UNII-3 Band IV PSD
IEEE 802.11a mode / 5725 ~ 5850MHz (chain 0)
5745MHz




Date: 30.JUL.2019 16:41:57

5785MHz




Date: 30.JUL.2019 16:49:00

5825MHz




Date: 30.JUL.2019 16:52:03

IEEE 802.11a mode / 5725 ~ 5850MHz (chain 1) 5745MHz



Date: 30.JUL.2019 16:40:12

5785MHz




Date: 30 JUL 2019 16:48:50

5825MHz




Date: 30 JUL 2019 16:51:49

IEEE 802.11a mode / 5725 ~ 5850MHz (chain 2)
5745MHz



Date: 30.JUL.2019 16:41:31

5785MHz



Date: 30.JUL.2019 16:48:20


5825MHz



Date: 30.JUL.2019 16:51:36

IEEE 802.11a mode / 5725 ~ 5850MHz (chain 3)

5745MHz




Date: 30.JUL.2019 16:40:32

5785MHz




Date: 30 JUL 2019 16:48:02

5825MHz




Date: 30 JUL 2019 16:51:19

IEEE 802.11ac VHT20 Mode / 5725 ~ 5850MHz (chain 0)
5745MHz




Date: 30 JUL 2019 16:55:19

5785MHz



Date: 30 JUL 2019 16:57:10

5825MHz



Date: 30 JUL 2019 16:53:38

IEEE 802.11ac VHT20 Mode / 5725 ~ 5850MHz (chain 1) 5745MHz



Date: 30 JUL 2019 16:55:00

5785MHz




Date: 30 JUL 2019 16:56:44

5825MHz



Date: 30 JUL 2019 16:53:17

IEEE 802.11ac VHT20 Mode / 5725 ~ 5850MHz (chain 2)
5745MHz




Date: 30.JUL.2019 16:54:43

5785MHz




Date: 30.JUL.2019 16:56:25

5825MHz




Date: 30 JUL 2019 16:53:02

IEEE 802.11ac VHT20 Mode / 5725 ~ 5850MHz (chain 3) 5745MHz




Date: 30 JUL 2019 16:54:30

5785MHz




Date: 30 JUL 2019 16:56:13

5825MHz




Date: 30 JUL 2019 16:52:49

IEEE 802.11ac VHT40 Mode / 5725 ~ 5850MHz (chain 0)
5755MHz




Date: 30.JUL.2019 16:31:19

5795MHz




Date: 30.JUL.2019 16:36:46

IEEE 802.11ac VHT40 Mode / 5725 ~ 5850MHz (chain 1)
5755MHz




Date: 30.JUL.2019 16:30:16

5795MHz




Date: 30.JUL.2019 16:36:34

IEEE 802.11ac VHT40 Mode / 5725 ~ 5850MHz (chain 2)
5755MHz




Date: 30.JUL.2019 16:31:02

5795MHz




Date: 30.JUL.2019 16:36:08

IEEE 802.11ac VHT40 Mode / 5725 ~ 5850MHz (chain 3)
5755MHz



Date: 30.JUL.2019 16:24:27


5795MHz



Date: 30.JUL.2019 16:35:51

IEEE 802.11ac VHT80 Mode / 5725 ~ 5850MHz (chain 0)


5775MHz



Date: 30.JUL.2019 16:23:05

IEEE 802.11ac VHT80 Mode / 5725 ~ 5850MHz (chain 1)


5775MHz



Date: 30.JUL.2019 16:22:53

IEEE 802.11ac VHT80 Mode / 5725 ~ 5850MHz (chain 2)


5775MHz



Date: 30.JUL.2019 16:22:42

IEEE 802.11ac VHT80 Mode / 5725 ~ 5850MHz (chain 3)

5775MHz



Date: 30.JUL.2019 16:22:29

***** END OF REPORT *****