



Compliance Statement in Car Manual

FCC ID: LTQJA125

IC: 3659A-JA125

Our client's products with the FCC ID and IC No. mentioned above are low frequency transmitters. The products will be installed in cars before they will be placed into the market.

Hereby our client assures that the following caution statement as per CFR 47, Part 15, §15.21 will be included in the owner's manual of the cars:

The title "CAUTION TO USERS" or "FCC Warning", "NOTE" or relevant title and "Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment."

In addition our client also assures that the following statement will be included in the manual as per FCC 15.19 / RSS Gen Issue 4 Sect. 8.4:

*This device complies with Part 15 of the FCC Rules and contains licence-exempt transmitter(s)/receiver(s) that comply with Innovation, Science and Economic Development Canada's licence-exempt RSS(s). Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.*

*Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes : (1) l'appareil ne doit pas produire de brouillage, et (2) l'utilisateur de l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.*

*To satisfy FCC exposure requirements a separation distance of 10 cm or more should be maintained between the antenna of this device and persons during operation. To ensure compliance, operations at closer distances than this are not recommended.*

*To satisfy FCC exposure requirements a separation distance of 10 cm or more should be maintained between the antenna of this device and persons during operation. To ensure compliance, operations at closer distances than this are not recommended.*

*Pour satisfaire aux exigences d'exposition ISED, une distance de séparation de 10 cm ou plus doit être maintenue entre l'antenne de cet appareil et les personnes pendant le fonctionnement. Pour assurer la conformité, les opérations à plus courte distance ne sont pas recommandées.*

Strasskirchen, August 30, 2018

Marion Musat

Project Specialist Global Market Access

CSA Group Bayern GmbH

CSA Group Bayern GmbH • Ohmstrasse 1 - 4 • 94342 Strasskirchen • GERMANY

Telefon: +49 (0) 9424 9481-0 • Telefax: +49 (0) 9424 9481-430 • E-Mail: info.bayern@csagroup.org • Web: www.csagroup.org

Geschäftsführer: Dieter Fröhlich, Peter Mertel, Kathryn Yung

Amtsgericht Straubing HRB 11130 • USt.-Id. Nr.: DE 814 397 903

Raiffeisenbank Straubing:

Kto: 5 580 080

BLZ: 742 601 10

IBAN: DE27 7426 0110 0005 5800 80

SWIFT (BIC): GENODEF1SR2

UniCredit Bank AG Straubing:

Kto: 345 753 540

BLZ: 742 200 75

IBAN: DE70 7422 0075 0345 7535 40

SWIFT (BIC): HYVEDEMM452