



# Intertek Testing Services

## ETL SEMKO

Report No.: 0300824  
Talk Mode


Tested By: Hong, Report No.: 0300824

Scan Settings (1 Range)

Frequencies				Receiver Settings			
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO LN	OFF 60dB

Final Measurement: x QP / + AV  
 Meas Time: 1 s  
 Subranges: 16  
 Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698





# Intertek Testing Services

ETL SEMKO

Report No.: 0300824  
Talk Mode

Tested By: Hong, Report No.: 0300824

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement

no Results