



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

March 9, 2006

RE: FCC ID: LW9-POCKET-MFSHL\_ATCB003249  
Attention: Michael A. Royer

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that the block diagram and parts list appears to show crystal Q301 in the transmitter circuitry. However, the actual schematics indicate Q1 and Q2 as the crystals, but give no frequency. Please explain and please correlate the block diagram with the actual schematics for the device.

Dennis Ward  
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.