



UNIVERSITY OF MICHIGAN
COLLEGE OF ENGINEERING
THE RADIATION LABORATORY
DEPARTMENT OF ELECTRICAL ENGINEERING
AND COMPUTER SCIENCE

3228 EECS BUILDING
1301 BEAL AVENUE
ANN ARBOR, MICHIGAN 48109-2122
734 764-0500 FAX 734 647-2106
<http://www.eecs.umich.edu/RADLAB/>

January 4, 2011

Certification and Engineering Bureau
Industry Canada
3701 Carling Avenue, Bldg. 94
Ottawa, Ontario K2H 8S2

Re: Certification for Continental Transmitter
Model/PN(s): SE10004
FCC ID: M3N5WY8817
IC: 7812A-5WY8817

Please find enclosed application materials for certification of Continental Transmitter.
We tested the device and found it to comply with RSS-GEN/102/210. The product is
identified by:

IC: 7812A-5WY8817

If there are any questions, suggestions, etc., regarding the application or testing
performed, please contact me at the above address or call 734-483-4211, fax 734-647-
2106; e-mail: liepa@umich.edu.

Sincerely,

A handwritten signature in cursive script that reads 'Valdis V. Liepa'.

Valdis V. Liepa
Research Scientist



UNIVERSITY OF MICHIGAN
COLLEGE OF ENGINEERING
THE RADIATION LABORATORY
DEPARTMENT OF ELECTRICAL ENGINEERING
AND COMPUTER SCIENCE

3228 EECS BUILDING
1301 BEAL AVENUE
ANN ARBOR, MICHIGAN 48109-2122
734 764-0500 FAX 734 647-2106
<http://www.eecs.umich.edu/RADLAB/>

January 4, 2011

Federal Communications Commission
Equipment Approval Services
P.O. Box 358315
Pittsburgh, PA 15251-5315

Re: Certification for Continental Transmitter
Model/PN(s): SE10004
FCC ID: M3N5WY8817
IC: 7812A-5WY8817

Please find enclosed application materials for certification of Continental Transmitter.
We tested it and found it to comply with FCC Part 15.

If there are any questions regarding the application or testing performed, please contact
me at the above address or call 734-483-4211, fax 734-647-2106, or e-mail
liepa@umich.edu.

Sincerely,

Valdis V. Liepa
Research Scientist