



**CONTINENTAL
MADE IN MEXICO**

**DG9T - 15604 -
BCM KIT ASSEMBLY
A2C7310880900
KEY CODE: 10335**



BG




YYDD000000

FCC ID: M3NA2C731087 IC: 7812A-A2C731087 M:A2C731087

This device complies with Part 15 of the FCC Rules and with Industry Canada license-exempt RSS standard(s). Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.





CONTINENTAL
MADE IN MEXICO

**DG9T - 15604 -
BCM KIT ASSEMBLY
A2C7329890800**



CG

KEY CODE: 10335

FCC ID: M3NA2C731087 IC: 7812A-A2C731087 M:A2C732988

YYDD000000

This device complies with Part 15 of the FCC Rules and with Industry Canada license-exempt RSS standard(s). Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.



DUT (bottom)

New Label Location

