

PHOTOS EXHIBIT

Report Number: R13156676-EP1

Applicant: Hunter Industries

1940 Diamond Street

San Marcos, CA 92078-5120 USA

Model: BTT-100/101

Contains FCC ID : M3UBTT1

Contains IC: 2772A-BTT1

EUT Description: Water Timer

Test Standard(s): FCC 47 CFR PART 15 SUBPART C

ISED RSS-247 ISSUE 2

ISED RSS-GEN ISSUE 5 + AMD 1

Date Of Issue:

2020-11-06

Prepared by:

UL LLC

12 Laboratory Dr.

Research Triangle Park, NC 27709 U.S.A.

TEL: (919) 549-1400



DATE: 2020-11-06 CONTAINS IC: 2772A-BTT1


REPORT REVISION HISTORY

Rev.	Issue Date	Revisions	Revised By
1	2020-11-06	Initial Issue	Mike Antola

TABLE OF CONTENTS

RE	PORT REVISION HISTORY	2
TAI	BLE OF CONTENTS	3
1.	SETUP DIAGRAMS	4
2	SETUD PHOTOS	5

1. SETUP DIAGRAMS




DATE: 2020-11-06


CONTAINS IC: 2772A-BTT1


2. SETUP PHOTOS


CONDUCTED RF MEASUREMENT SETUP





RADIATED RF MEASUREMENT SETUP














DATE: 2020-11-06 CONTAINS IC: 2772A-BTT1

END OF PHOTOS EXHIBIT