

Sep. 10, 2002

Federal Communication Commission
Authorization & Evaluation Laboratories
7435 Oakland Mills Rd.
Columbia MD 21046

Attn: Mr. Joe Dichoso

Regarding to your review comments, please see the response listed as below:

- 1) The antenna connector type is MMCX-Reverse, Polarization Pin.
- 2) We had re-tested the EMC test under FCC 15.247 and uploaded on 8/30, 2002.
Please find the report as one of attachment. (File name: report)
- 3) We had modified the RF exposure statement of manual as your requirement and uploaded on 8/30, 2002. Please also find the manual as one of attachments. (File name: Installation guide)

I hope the attachments satisfy all your requirements for reviewing this application.
If you have any questions, please feel free to contact me.

Best Regards,



Elton Chen

Supervisor

Intertek Testing Service Taiwan Ltd.

E-mail: echan@itslabtest-twn.com