Dear Timothy

Thank you for your comments.

About comment 1: Our engineer mistook, he added the cable less(2.14dBi) to reading, so we modified the test report and upload to ATCB website, the file name as "Test Report-revised" About comment 2: We tested(SAR) again and upload to ATCB website, the file name as "SAR Report"

If you have any question, please feel free to let me know.

Thank you

Best regards Sunny