



Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch
香港商立德國際商品試驗有限公司桃園分公司

14th Ling, Chiapau Tsuen, Linkou, Taipei, Taiwan, R.O.C.
<http://www.adt.com.tw/> E-mail: service@adt.com.tw

台北縣林口鄉嘉寶村 14 鄰 47 號
 TEL: 886-2-26052180 FAX: 886-2-26051924

September 21, 2010

Re: Supersede request for FCC ID: M6E-FAB3540-1; Granted on **09/07/2010**

To Whom It May Concern:

We would like to upload the revised test report .Since the rated power supply is wrong on original report. It shall be 1.5Vdc not 3Vdc.This is our oversight to cause the error. This error doesn't effect the test result.

Revised page is P4 and 5

P4

APPLIED STANDARD: FCC Part 15, Subpart C (Section 15.249)			
STANDARD PARAGRAPH	TEST TYPE	RESULT	REMARK
15.207	Conducted Emission Test	NA	Power supply is 1.5Vdc from battery.

P5

EUT	WX-LAMBORGHINI WIRELESS LASER MOUSE
MODEL NO.	WX-LAMBOR MOUSE
FCC ID	M6E-FAB3540-1
POWER SUPPLY	1.5Vdc

If you have any questions, feel free to contact us. Thank you.

Sincerely yours,

Gary Chang
 Assistant Manager
 Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch
 Tel: 886-3-3183232 ext. 1608
 Fax: 886-3-3270892
 Email: Gary_chang@ adt.com.tw