

Fego Precision Industrial Co., Ltd.

947, Lin-Sen Road,
Wu-Fong, Tai-Chung, 413, Taiwan, ROC
Tel: 886-4-3391802 Fax: 886-4-3399374

September 29, 2000

Dear Sir:

We have received your fax at September 21. The issues you mentioned about are replied as follows:

The differences between the BC-9064 and the RL202 (FCC ID: M8CRL202) are:

- a) The layout of the PBC is different.
- b) The BC-9064 uses VC to adjust its frequency.

The differences between the BC-9062 and the BC9006 (FCC ID: M8CBC9006) are:

- a) The layout of the PBC is different.
- b) The BC-9062 has the larger LED.
- c) The BC-9062 has four extra function keys.
- d) The smaller RF module of the BC-9062 is laid on the PBC directly.

Sincerely,

Chien Fong Lin

Chien-Fong Lin