

Fego Precision Industrial Co., Ltd.

947, Lin-Sen Road,
Wu-Fong, Tai-Chung, 413, Taiwan, ROC
Tel: 886-4-3391802 Fax: 886-4-3399374

06/01/2004

Dear Sir:

The differences between the BC4162D and the RL202 (FCC ID: M8CRL202) are:

- a) The layout of the PCB is different.
- b) The ANT Type change.

Sincerely,

Chien Fong Lin

Chien-Fong Lin