

HITACHI**Hitachi Home Electronics (Europe) Ltd**
Manufacturing DivisionHirwaun Industrial Estate, Aberdare,
Mid Glamorgan, CF44 9UY
Tel 01685 811451 Fax: 01685 814611

Ref. 00082

*12 August 1998*Federal Communications Commission
Applications Processing Branch
7435 Oakland Mills Road
Columbia
Maryland 21046

Dear Sir

Subject: Location of the FCC ID label

This is to declare that the FCC ID label will be located on the rear of the monitor in production.

This FCC ID label will be a part of the equipment identification (rating) label and will be permanently affixed to the equipment.

This location is indicated in Fig. No. **2** within the Form 731 Assembly.

Yours faithfully



Mr. O. Miwada
Executive Manager - Quality
for and on behalf of
Hitachi Home Electronics (Europe) Ltd



Apparätet må kun tillkoplas jordet stikkontakt.
 Apparatet skall anslutas till jordat uttag när den
 ansluts till ett nätverk.
 Laite on liitettävä suojakosketinpiistorasiaan.

Die in diesem Gerät erzeugte Röntgenstrahlung ist durch
 die eigensichere Kathodenstrahlröhre ausreichend
 abgeschirmt. Beschleunigungsspannung geräte technisch
 begrenzt auf maximal 28 kV. Maximaler Strahlstrom 1000µA

WARNING:

- A) THIS APPARATUS MUST BE EARTHED.
 B) LIVE PARTS ARE MADE ACCESSIBLE WHEN BACK COVER IS
 REMOVED.
 C) ALWAYS REMOVE MAINS PLUG FROM WALL SOCKET BEFORE
 ANY SERVICE OPERATIONS, NEVER REMOVE COVERS UNLESS
 QUALIFIED TO DO SO. THIS UNIT
 CONTAINS DANGEROUS VOLTAGES.

SIEMENS

Siemens AG
 Bgm.-Ulrich-Str.100, 86199 Augsburg
 Fed. Rep. of Germany
 Farb-Monitor MCM 212V

S26361-K539-V150
 100-120V / 200V-240V
 50/60Hz 1.4A/0.7A

X-RAY EMISSION: MONITOR COMPLIES WITH DHHS RULES 21
 CFR SUBCHAPTER J APPLICABLE AT DATE OF MANUFACTURE.
 THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES.
 OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS:
 (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND
 (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED,
 INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRABLE
 OPERATION.

THIS CLASS B APPARATUS MEETS ALL REQUIREMENTS OF THE
 CANADIAN INTERFERENCE-CAUSING EQUIPMENT REGULATIONS.
 CET APPAREIL NUMÉRIQUE DE LA CLASSE B RESPECTE TOUTES
 LES EXIGENCES DU RÉGLEMENT SUR LE MATÉRIEL BROUILLÉUR
 DU CANADA.

CHASSIS NO. DJ81
 MADE IN U.K.

FCC ID: M9U9801DJ81MD



LR108739



DP



LISTED
 7J88
 UL1950
 E132107



X9999999

MH14238

Siemens Nixdorf Informationssysteme AG Bismarckstr. 106, 81199 Augsburg Fed. Rep. of Germany Farb-Monitor MCM 211V S:26361-K5039-V150	FCC ID M9U 9801MD	X-RAY IMMISSION MONITOR COMPLIES WITH EN61321-21 OFF SUBCHAPTER J APPLICABLE AT DATE OF MANUFACTURE. THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRABLE OPERATION.	Apparat mit dem theoretisch jeder elektronische Apparat ausstrahlt, ist jedoch unter der Bedingung, dass er nicht stört. Die in diesem Gerät erzeugte Störleistung ist durch die elektrische Abschirmung des Gehäuses begrenzt auf maximal 28 V. Maximumstrom 1000µA.
SIEMENS NIXDORF			
ALL THIS APPARATUS MUST BE EARTHED. IF LIVE PARTS ARE MADE ACCESSIBLE WHEN BACK COVER IS REMOVED. C) ALWAYS REMOVE MAINS PLUS FROM WALL SOCKET BEFORE ANY REPAIRS. OPERATORS: NEVER WORK ON COVER UNLESS QUALIFIED TO DO SO. THIS UNIT CONTAINS CAPACITORS VOL. 1000V. MADE IN U.K. MH17861 3871794 p			