

BRIDGELINK-PRO (5.775 GHz)



FCC ID: MCI-397

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference relieved, including interference that may cause undesired operations

RMAC

EMAC

ITE

Made in the U.S.A. © RadioLAN, Inc. 2003

 ϵ

RMG-397

Pr A B C D E F G H J K Pt 0 1 2 3 4 5 6 7 8

RMG-397 Rev A



Power-on-Ethernet **Injector**

Note: To avoid damage to Ethernet Equipment, connect cables according to the instructions in the Users Manual.

Radíolan

BRIDGELINK-PRO (5.775 GHz)



FCC ID: MCI-397

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference relieved, including interference that may cause undesired operations

RMAC

EMAC

LISTED

Made in the U.S.A. © RadioLAN, Inc. 2003

RMG-397

ABCDEFGHJK 1 2 3 4 5 6 7 8 9

RMG-397 Rev 4

CE

Ethernet Surge Supressor



Power-on-Ethernet Injector

Note: To avoid damage to Ethernet Equipment, connect