



DIGI INTERNATIONAL

9350 Excelsior Blvd, Suite 700

Hopkins, MN 55343, USA

Tel: +1 (952) 912-3444

Fax: +1 (952) 912-4991

October 22, 2021

Federal Communications Commission  
Authorization and Evaluation Division  
7435 Oakland Mills Road  
Columbia, Maryland 21046

**Re: Cover Letter: Non-SDR for FCC ID: MCQ-EX50W**

To whom it may concern:

The following five questions determine that the radio is **not an SDR**:

1. Can the RF parameters of the device be altered through software?

Yes, go to question 2. No, not an SDR.

**MCQ-EX50W: Yes**

2. Can third parties not permitted by the Commission through specific filings modify, configure, or load different software, or make configuration settings to operate the device or host hardware radio frequency parameters in any other way than expected to be granted?

Yes, must be an SDR. No, go to question 3.

**MCQ-EX50W: No**

3. Is the device capable of operating in any other in any other way than granted, or will be, granted?

Yes, go to question 4. No, go to question 5.

**MCQ-EX50W: No**

4. [Question not applicable]

5. Does the manufacturer elect SDR?

Yes, elects to be an SDR. No, not an SDR.

**MCQ-EX50W: No**

Sincerely,

---

Name: Harald Remmert

Title: Sr. Director of Engineering