

Correspondence by Project

Project Number:

1450383341

Correspondence Number	Memo
MG3-2010-1	1) Please provide an explanation on how the device meets the operational requirements of 15.231. Response: The Transmitter turns off immediately after a button is released. The Tx configuration data clock pin remains on for 74us after the FSK data has been processed.