



April 26, 2000

Mr. Tim Johnson  
US Tech  
3505 Francis Circle  
Alpharetta, GA. 30201

Dear Tim:

This letter is in response to the FCC request for more information regarding labeling of the Hornet radio. All units will contain a FCC Identification label on the shield per the enclosed labeling description.

The Operators Manual will be updated to notify all users that all products containing the Hornet radio must be clearly marked with an external label stating the following: "Contains FCC ID: MH9-HNT2400". In addition, Xetron will make these labels available to all customers.

Sincerely,

Larry P. Ochs  
Product Manager