To: "Timothy R. Johnson" <TRJ@adelphia.net> Cc: amanda@adt.com.tw Subject: =?big5?B?pl6rSKFHIFJIOiBSZXZpc2VkIENvbW1lbnRzIFJIZ2FyZGluZw==?= Application FCC ID: MIBRF50702-02

Dear Timothy,

Thanks for your kind help on this project. Here are our reply for the comments,

1) the antenna connector is a Reversed SMA type, it is not normal connector.

2) all laptop description were deleted, the correct user's manual will be put on ATCB site.

3) the FCC ID has been corrected on the user's manual.

4) It is our mistake, the conducted power has been corrected and the correct 731 Form will be put on ATCB site.

For above, if you have any further questions or comments, please feel free to contact us.

Best Regards,

Eric Lin ADT Hsinchu lab.