



Enfora, L.P.
661 E. 18th Street
Plano, TX 75074-5601
(972) 633-4400
Fax (972) 633-4444

GSM3208 Tune-Up Procedure

The Enfora GSM3208 contains an Enfora GSM0108 Modem. The GSM0108 Modem does not allow for any user adjustments to frequency or power output. In normal operation, the GSM network tunes the GSM0108's radio and sets the power level.

Date: June 2, 2004

By: Scott Yarberry

A handwritten signature in black ink that reads "Scott Yarberry". The signature is written in a cursive, flowing style.

Title: Sr. Director, Product Development

Telephone: 972-633-3560

Applicant: Enfora, L.P., 661 E. 18th St., Plano, TX 75074