



Enfora, Inc.  
661 E. 18<sup>th</sup> Street  
Plano, TX 75074-5601  
(972) 633-4400  
Fax (972) 633-4444

December, 2006

## **Tune-Up Procedure Description for GSM3408**

### Power Adjustments

The RF power output of the modem is preset during the manufacturing process via software-controlled adjustment of calibration parameters referenced to a base-station simulator.

In normal operation, the RF output power is maintained via an ALC circuit. The end-user does not have access to the calibration/power adjustment of the device.

### Frequency Adjustments

The transceiver uses a frequency synthesizer that is synchronized to the cell phone system's base-station clock. No frequency alignments are needed.

Scott Yarberry

A handwritten signature in black ink that reads "Scott Yarberry". The signature is written in a cursive, flowing style.

AVP, Product Development  
Enfora, Inc.  
661 E. 18<sup>th</sup> St  
Plano, TX 75074  
972-633-4400