

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Attention: Application Examiner/ Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: FCC ID: **MJBWCC201G**

To The Commission:

This Change of Identification request applies for a new FCC ID as established in 47CFR 2.933(b) for a currently approved device. This application by Allied Telesyn Inc. will establish a new FCC ID under Allied Telesyn Inc. grantee code for purpose of marketing. The original grant to Atheros Communications ,Inc FCC ID:PPD-AR5BCB-00051. will remain in effect.

An authorization letter by **Atheros Communications ,Inc** is attached.


Per 2.933(b)

1. The original identification is FCC ID: PPD-AR5BCB-00051.
2. The original grant date is 05/18/2004
3. The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter
External Photos
FCC ID label format and location

Sincerely,



Name: Robert R. Blackmer
Title: Director of Compliance Engineering
Date: January 16, 2006

Toll Free 800.734.4284

3200 North First Street, San Jose, CA 95134

www.alliedtelesyn.com

It's Our Network, Too.