


**APPENDIX 3: Photographs of test setup**

**Radiated emission**



**Photo 1**



**Photo 2**

---

**UL Japan, Inc.**

**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

**Worst case position**  
**(Horizontal: X-axis/Vertical : Y-axis)**

**X-axis**



**Y-axis**



**Z-axis**



---

**UL Japan, Inc.**

**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

**Worst case position**



**Mechanical Key (Inserted)  
Worst Above 1GHz**



**Mechanical Key (Not Inserted)  
Worst Below 1GHz**



**Mechanical Key (Not Inserted)**



**Mechanical Key (Not Inserted)**

**End of Report**