

Mr. Andy Leimer
Re: FCC ID: MMA75511; EA98410
Midland Consumer Radio
Correspondence Reference #16116
FCC Inquiry Dated 9/14/00

1. Push-to-talk devices, per Kwok Chan, duty factory inherently does not exceed 50%.
- 2/3 User instructions have been revised to include warning statement that device should not be operated in body-worn configuration, see Page 3.