



April 15, 2004

Mr. Stan Lyles
Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21045

Ref: Midland Radio Corporation's FCC ID: MMA80151
Correspondence ID # 26549

Dear Mr. Lyles:

In response to your email request of 3/22/04, correspondence ID 26549;

1. I spoke with Tim Harrington regarding the SAR results with the second antenna and advised him that the SAR report did, in fact, contain SAR results with both antennas. He agreed that he had overlooked this in the SAR report and it was in there.
2. I've uploaded a revised user's manual regarding the VOX mode. The manufacturer has also stated:

"Regarding antenna selection the user will only receive 1 antenna chosen by the dealer. We supply fixed frequency VHF antennas that do not cover the entire radios operating band width. The dealer programming the radio selects the properly matched antenna to the users operating frequencies upon ordering the radio."

3. The 731 form was incorrect in stating 20.0 ppm. Please correct it to ready 5.0 ppm.

Should you have any further questions, please advise.

Regards,

A handwritten signature in blue ink that reads "Sharon Hoffman".

Sharon Hoffman