



March 24, 2009


RE: Permissive change to model id:MMAGXT950

These changes are now made to the GXT950 to make the new models GXT1000 and GXT1050:


Transmitter driver stage change for reason of economy:

GXT900/950 driver stage is composed 3pcs of BFQ67W (Q3,Q4, Q4A), while GXT1000/1050 driver stage is using 1 RF Amp NESG250134.





old mic ckt



Midland Radio Corporation
5900 Parretta Drive, Kansas City, MO. 64120 Phone: (816) 241-8500 Fax: (816) 241-5713
Website: www.midlandradio.com E-Mail: mail@midlandradio.com



5900 Parretta Drive • KANSAS CITY, MISSOURI • 64120
TELEPHONE: (816) 241-8500 • FAX: (816) 241-5713
EMAIL: mail@midlandradio.com
WEBSITE: www.midlandradio.com

Sincerely Yours,

A handwritten signature in black ink that reads "David Kingsolver". The signature is fluid and cursive, with a long horizontal stroke at the end.

David Kingsolver, Engineering manager
Midland Radio Corporation
davidk@midlandradio.com
(816) 462-0437

Midland Radio Corporation

5900 Parretta Drive, Kansas City, MO. 64120 Phone: (816) 241-8500 Fax: (816) 241-5713
Website: www.midlandradio.com E-Mail: mail@midlandradio.com