



AboCom Systems, Inc.

Head Office: 1F, No. 21, R&D Rd. II, SBIP, Hsin-Chu 300, Taiwan.

Factory: No. 77, Yu-Yih Rd., Chu-Nan Chen, Miao-Lih Hsian 350, Taiwan.

Taipei Office: 4F, No.130-2, Lane 235, Bao-Chiao Rd., Sindian Dist., New Taipei City 23145, Taiwan.

TEL: +886-37-580-777

FAX: +886-37-580-799

<http://www.abocom.com.tw>

Subject : Request to change in Identification.

Dear Regulatory Authority,

This Change of Identification request applies for a new FCC ID: as established in 47CFR 2.933(b) for a currently approved device. This application by Abocom will establish a new FCC ID: MQ4-VM331R under Abocom grantee code for purpose of marketing. The original grant to Silicon Image will remain in effect.

Per 2.933(b)

1. The original identification is UK2-SII-SK63101
2. The original grant date is 05/19/2012
3. The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter

External Photos

FCC ID label format and location

Sincerely,

Signature

Alex Char

A handwritten signature in cursive script that reads "Alex Char".

Assistant Vice President

AboCom Systems, Inc.