

Re: FCC ID: MQ5FM-08-TX

Applicant: Telean Technology Ltd
Correspondence Reference Number: 3324
731 Confirmation Number: TC359818
Date of Original Email: 12/21/2001

Subject:

1). The field strength levels of spurious emissions at 249.5 MHz and 598.8 MHz exceed that of the fundamental at 49.9 MHz on channel 3. This is in violation of Section 15.209(c) of the Commission's Rules. Please address.

Note that future applications which exhibit this violation will be set aside.

[Uploaded revised report "010802 test report".](#)

The harmonics, at 249.5MHz and 598.8MHz, and the site correction factors were re-measured and corrected. It was found that the harmonic levels comply with Part 15.209(c).

2). The schematic is not legible. Submit a clearer version. 3). Provide requirements for information to the user per Section 15.21.

[Uploaded jpg file. Hopefully this will be clear enough.](#)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal pursuant to Section 2.917(c).