



Intertek Testing Services

ETL SEMKO

Report No.: 0213097

Tested By: Ben, Report No.: 0213097

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



PAGE 1

Ctrl No.:



Intertek Testing Services

ETL SEMKO

Report No.: 0213097

Tested By: Ben, Report No.: 0213097

Scan Settings (1 Range)

----- Frequencies -----			----- Receiver Settings -----					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement
Results:

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV
0.58500	30.4	48.0
0.59000	30.5	48.0
0.87500	31.7	48.0
1.26500	31.3	48.0
1.36000	29.1	48.0
2.14000	28.6	48.0
2.24000	30.6	48.0
5.93500	24.1	48.0
6.33000	24.0	48.0
13.56500	26.5	48.0
13.66000	18.6	48.0
22.27000	24.4	48.0

* limit
exceeded

Ctrl No.: