




NOTE: FCC and IC LABEL WILL BE CORRECTED AS DETAILED IN ATTACHED DRAWING.



NORMAL 500

TPMS SENSOR TOOL



Ford Motor Company

8C2T-1A203-AB

FCC ID: MRXFLF1MA4

IC: 2546A-FLF1MA4