





11AX20MIMO_Ant.5+6(6)_6535_52Tone_RU37



Date: 22.APR.2022 10:25:43


11AX20MIMO_Ant.5+6(6)_6535_106Tone_RU53



Date: 22.APR.2022 10:26:47




11AX20MIMO_Ant.5+6(5)_6695_26Tone_RU4



Date: 22.APR.2022 10:28:50


11AX20MIMO_Ant.5+6(5)_6695_52Tone_RU38



Date: 22.APR.2022 10:31:08




11AX20MIMO_Ant.5+6(5)_6695_106Tone_RU53



Date: 22.APR.2022 10:32:04


11AX20MIMO_Ant.5+6(6)_6695_26Tone_RU4



Date: 22.APR.2022 10:29:25




11AX20MIMO_Ant.5+6(6)_6695_52Tone_RU38



Date: 22.APR.2022 10:30:32


11AX20MIMO_Ant.5+6(6)_6695_106Tone_RU53



Date: 22.APR.2022 10:32:33




11AX20MIMO_Ant.5+6(5)_6855_26Tone_RU8



Date: 22.APR.2022 10:34:25


11AX20MIMO_Ant.5+6(5)_6855_52Tone_RU40



Date: 22.APR.2022 10:35:27




11AX20MIMO_Ant.5+6(5)_6855_106Tone_RU54



Date: 22.APR.2022 10:37:25


11AX20MIMO_Ant.5+6(6)_6855_26Tone_RU8



Date: 22.APR.2022 10:33:58




11AX20MIMO_Ant.5+6(6)_6855_52Tone_RU40



Date: 22.APR.2022 10:35:59


11AX20MIMO_Ant.5+6(6)_6855_106Tone_RU54



Date: 22.APR.2022 10:36:57




11AX20MIMO_Ant.5+6(5)_6875_26Tone_RU8



Date: 22.APR.2022 10:38:23


11AX20MIMO_Ant.5+6(5)_6875_52Tone_RU40



Date: 22.APR.2022 10:40:40




11AX20MIMO_Ant.5+6(5)_6875_106Tone_RU54



Date: 22.APR.2022 10:41:45


11AX20MIMO_Ant.5+6(6)_6875_26Tone_RU8



Date: 22.APR.2022 10:38:57




11AX20MIMO_Ant.5+6(6)_6875_52Tone_RU40



Date: 22.APR.2022 10:40:13


11AX20MIMO_Ant.5+6(6)_6875_106Tone_RU54



Date: 22.APR.2022 10:42:15




11AX20MIMO_Ant.5+6(5)_6895_26Tone_RU0



Date: 22.APR.2022 10:56:46


11AX20MIMO_Ant.5+6(5)_6895_52Tone_RU37



Date: 22.APR.2022 11:00:19




11AX20MIMO_Ant.5+6(5)_6895_106Tone_RU53



Date: 22.APR.2022 11:01:31


11AX20MIMO_Ant.5+6(6)_6895_26Tone_RU0



Date: 22.APR.2022 10:57:38




11AX20MIMO_Ant.5+6(6)_6895_52Tone_RU37



Date: 22.APR.2022 10:58:46


11AX20MIMO_Ant.5+6(6)_6895_106Tone_RU53



Date: 22.APR.2022 10:59:49




11AX20MIMO_Ant.5+6(5)_6995_26Tone_RU4



Date: 22.APR.2022 11:01:31


11AX20MIMO_Ant.5+6(5)_6995_52Tone_RU38



Date: 22.APR.2022 11:25:19




11AX20MIMO_Ant.5+6(5)_6995_106Tone_RU53



Date: 22.APR.2022 11:22:27


11AX20MIMO_Ant.5+6(6)_6995_26Tone_RU4



Date: 22.APR.2022 11:02:01




11AX20MIMO_Ant.5+6(6)_6995_52Tone_RU38



Date: 22.APR.2022 11:24:53


11AX20MIMO_Ant.5+6(6)_6995_106Tone_RU53



Date: 22.APR.2022 11:23:50




11AX20MIMO_Ant.5+6(5)_7095_26Tone_RU8



Date: 21.MAY.2022 02:34:01


11AX20MIMO_Ant.5+6(5)_7095_52Tone_RU40



Date: 21.MAY.2022 02:37:47




11AX20MIMO_Ant.5+6(5)_7095_106Tone_RU54



Date: 21.MAY.2022 02:37:47


11AX20MIMO_Ant.5+6(6)_7095_26Tone_RU8



Date: 21.MAY.2022 02:34:33




11AX20MIMO_Ant.5+6(6)_7095_52Tone_RU40



Date: 21.MAY.2022 02:37:15


11AX20MIMO_Ant.5+6(6)_7095_106Tone_RU54



Date: 21.MAY.2022 02:39:14




11AX20MIMO_Ant.5+6(5)_7115_26Tone_RU8



Date: 17.JUN.2022 11:10:04


11AX20MIMO_Ant.5+6(5)_7115_52Tone_RU40



Date: 17.JUN.2022 11:12:17




11AX20MIMO_Ant.5+6(5)_7115_106Tone_RU54



Date: 17.JUN.2022 11:15:10


11AX20MIMO_Ant.5+6(6)_7115_26Tone_RU8



Date: 17.JUN.2022 11:10:50




11AX20MIMO_Ant.5+6(6)_7115_52Tone_RU40



Date: 17.JUN.2022 11:13:54


11AX20MIMO_Ant.5+6(6)_7115_106Tone_RU54



Date: 17.JUN.2022 11:15:58




11AX40MIMO_Ant.5+6(5)_5965_242Tone_RU61



Date: 22.APR.2022 11:32:10


11AX40MIMO_Ant.5+6(6)_5965_242Tone_RU61



Date: 22.APR.2022 11:33:00




11AX40MIMO_Ant.5+6(5)_6165_242Tone_RU61



Date: 22.APR.2022 11:34:28


11AX40MIMO_Ant.5+6(6)_6165_242Tone_RU61



Date: 22.APR.2022 11:33:57




11AX40MIMO_Ant.5+6(5)_6405_242Tone_RU62



Date: 22.APR.2022 11:35:38


11AX40MIMO_Ant.5+6(6)_6405_242Tone_RU62



Date: 22.APR.2022 11:36:32




11AX40MIMO_Ant.5+6(5)_6445_242Tone_RU61



Date: 22.APR.2022 11:38:00


11AX40MIMO_Ant.5+6(6)_6445_242Tone_RU61



Date: 22.APR.2022 11:37:31




11AX40MIMO_Ant.5+6(5)_6485_242Tone_RU62



Date: 22.APR.2022 11:39:08


11AX40MIMO_Ant.5+6(6)_6485_242Tone_RU62



Date: 22.APR.2022 11:39:35




11AX40MIMO_Ant.5+6(5)_6525_242Tone_RU62



Date: 22.APR.2022 12:21:14


11AX40MIMO_Ant.5+6(6)_6525_242Tone_RU62



Date: 22.APR.2022 12:20:44




11AX40MIMO_Ant.5+6(5)_6565_242Tone_RU61



Date: 22.APR.2022 12:22:06


11AX40MIMO_Ant.5+6(6)_6565_242Tone_RU61



Date: 22.APR.2022 12:22:35




11AX40MIMO_Ant.5+6(5)_6685_242Tone_RU61



Date: 22.APR.2022 12:24:16


11AX40MIMO_Ant.5+6(6)_6685_242Tone_RU61



Date: 22.APR.2022 12:23:47




11AX40MIMO_Ant.5+6(5)_6845_242Tone_RU62



Date: 22.APR.2022 12:25:22


11AX40MIMO_Ant.5+6(6)_6845_242Tone_RU62



Date: 22.APR.2022 12:25:51




11AX40MIMO_Ant.5+6(5)_6885_242Tone_RU61



Date: 22.APR.2022 12:28:12

11AX40MIMO_Ant.5+6(6)_6885_242Tone_RU61



Date: 22.APR.2022 12:27:41