



Test Report N° 210209-01.TR30




Date: 24.JUN.2021 12:59:49

-BE-NR-LOW, SISO-A, 802.11ax20-HE0, Ch177




-BE-NR-HIGH, SISO-A, 802.11ax20-HE0, Ch177




Date: 24.JUN.2021 13:00:55

-BE-NR-LOW, SISO-A, 802.11ax40-HE0, Ch167




-BE-NR-HIGH, SISO-A, 802.11ax40-HE0, Ch167




Date: 24.JUN.2021 16:10:32

-BE-NR-LOW, SISO-A, 802.11ax40-HE0, Ch175




-BE-NR-HIGH, SISO-A, 802.11ax40-HE0, Ch175




Date: 24.JUN.2021 16:13:02

-BE-NR-LOW, SISO-A, 802.11ax80.HE0, Ch171




-BE-NR-HIGH, SISO-A, 802.11ax80.HE0, Ch171




Date: 24.JUN.2021 13:04:16

-BE-NR-LOW, SISO-A, 802.11ax160-HE0, Ch163




-BE-NR-HIGH, SISO-A, 802.11ax160-HE0, Ch163




Date: 24.JUN.2021 18:40:03

BE-NR-LOW, SISO-B, 802.11a20-6Mbps, Ch169




BE-NR-HIGH, SISO-B, 802.11a20-6Mbps, Ch169




Date: 24.JUN.2021 18:41:09

BE-NR-LOW, SISO-B, 802.11a20-6Mbps, Ch173




BE-NR-HIGH, SISO-B, 802.11a20-6Mbps, Ch173




Date: 24.JUN.2021 18:42:15

BE-NR-LOW, SISO-B, 802.11a20-6Mbps, Ch177




BE-NR-HIGH, SISO-B, 802.11a20-6Mbps, Ch177




Date: 24.JUN.2021 18:43:22

BE-NR-LOW, SISO-B, 802.11n20-HT0, Ch169




BE-NR-HIGH, SISO-B, 802.11n20-HT0, Ch169




Date: 24.JUN.2021 18:44:29

BE-NR-LOW, SISO-B, 802.11n20-HT0, Ch173




BE-NR-HIGH, SISO-B, 802.11n20-HT0, Ch173




Date: 24.JUN.2021 18:45:35

BE-NR-LOW, SISO-B, 802.11n20-HT0, Ch177




BE-NR-HIGH, SISO-B, 802.11n20-HT0, Ch177




Date: 24.JUN.2021 18:43:41

BE-NR-LOW, SISO-B, 802.11n40-HT0, Ch167




BE-NR-HIGH, SISO-B, 802.11n40-HT0, Ch167




Date: 25.JUN.2021 09:00:02

BE-NR-LOW, SISO-B, 802.11n40-HT0, Ch175




BE-NR-HIGH, SISO-B, 802.11n40-HT0, Ch175




Date: 24.JUN.2021 19:19:37

BE-NR-LOW, SISO-B, 802.11ac80-VHT0, Ch171




BE-NR-HIGH, SISO-B, 802.11ac80-VHT0, Ch171




Date: 24.JUN.2021 19:25:38

BE-NR-LOW, SISO-B, 802.11ac160-VHT0, Ch163




BE-NR-HIGH, SISO-B, 802.11ac160-VHT0, Ch163

Test Report N° 210209-01.TR30




Date: 24.JUN.2021 18:51:03

BE-NR-LOW, SISO-B, 802.11ax20-MCS0, Ch169




BE-NR-HIGH, SISO-B, 802.11ax20-MCS0, Ch169




Date: 24.JUN.2021 18:52:14

BE-NR-LOW, SISO-B, 802.11ax20-MCS0, Ch173




BE-NR-HIGH, SISO-B, 802.11ax20-MCS0, Ch173




Date: 24.JUN.2021 18:53:21

BE-NR-LOW, SISO-B, 802.11ax20-MCS0, Ch177




BE-NR-HIGH, SISO-B, 802.11ax20-MCS0, Ch177




Date: 24.JUN.2021 18:54:27

BE-NR-LOW, SISO-B, 802.11ax40-MCS0, Ch167




BE-NR-HIGH, SISO-B, 802.11ax40-MCS0, Ch167




Date: 25.JUN.2021 09:04:43

BE-NR-LOW, SISO-B, 802.11ax40-MCS0, Ch175




BE-NR-HIGH, SISO-B, 802.11ax40-MCS0, Ch175




Date: 24.JUN.2021 19:27:34

BE-NR-LOW, SISO-B, 802.11ax80-MCS0, Ch171




BE-NR-HIGH, SISO-B, 802.11ax80-MCS0, Ch171

Test Report N° 210209-01.TR30




Date: 24.JUN.2021 19:29:15

BE-NR-LOW, SISO-B, 802.11ax160-MCS0, Ch163




BE-NR-HIGH, SISO-B, 802.11ax160-MCS0, Ch163




Date: 24.JUN.2021 14:09:30

BE-NR-LOW, MIMO-A, 802.11n20-HT8, Ch169




BE-NR-HIGH, MIMO-A, 802.11n20-HT8, Ch169




Date: 24.JUN.2021 14:10:37

BE-NR-LOW, MIMO-A, 802.11n20-HT8, Ch173




BE-NR-HIGH, MIMO-A, 802.11n20-HT8, Ch173






Date: 24.JUN.2021 14:11:44

BE-NR-LOW, MIMO-A, 802.11n20-HT8, Ch177




BE-NR-HIGH, MIMO-A, 802.11n20-HT8, Ch177




Date: 24.JUN.2021 14:12:52

BE-NR-LOW, MIMO-A, 802.11n40-HT8, Ch167




BE-NR-HIGH, MIMO-A, 802.11n40-HT8, Ch167




Date: 24.JUN.2021 15:07:51

BE-NR-LOW, MIMO-A, 802.11n40-HT8, Ch175



BE-NR-HIGH, MIMO-A, 802.11n40-HT8, Ch175

Test Report N° 210209-01.TR30




Date: 24.JUN.2021 15:12:30

BE-NR-LOW, MIMO-A, 802.11ac80-VHT0, Ch171



BE-NR-HIGH, MIMO-A, 802.11ac80-VHT0, Ch171




Date: 24.JUN.2021 15:19:15

BE-NR-LOW, MIMO-A, 802.11ac160-VHT0, Ch163




BE-NR-HIGH, MIMO-A, 802.11ac160-VHT0, Ch163




Date: 24.JUN.2021 14:17:33

BE-NR-LOW, MIMO-A, 802.11ax20-MCS0, Ch169




BE-NR-HIGH, MIMO-A, 802.11ax20-MCS0, Ch169

Test Report N° 210209-01.TR30




Date: 24.JUN.2021 14:18:42

BE-NR-LOW, MIMO-A, 802.11ax20-MCS0, Ch173




BE-NR-HIGH, MIMO-A, 802.11ax20-MCS0, Ch173




Date: 24.JUN.2021 14:19:51

BE-NR-LOW, MIMO-A, 802.11ax20-MCS0, Ch177




BE-NR-HIGH, MIMO-A, 802.11ax20-MCS0, Ch177




Date: 24.JUN.2021 14:21:01

BE-NR-LOW, MIMO-A, 802.11ax40-MCS0, Ch167




BE-NR-HIGH, MIMO-A, 802.11ax40-MCS0, Ch167




Date: 24.JUN.2021 15:23:24

BE-NR-LOW, MIMO-A, 802.11ax40-MCS0, Ch175




BE-NR-HIGH, MIMO-A, 802.11ax40-MCS0, Ch175




Date: 24.JUN.2021 15:32:09

BE-NR-LOW, MIMO-A, 802.11ax80-MCS0, Ch171




BE-NR-HIGH, MIMO-A, 802.11ax80-MCS0, Ch171




Date: 24.JUN.2021 15:34:16

BE-NR-LOW, MIMO-A, 802.11ax160-MCS0, Ch163




BE-NR-HIGH, MIMO-A, 802.11ax160-MCS0, Ch163

Test Report N° 210209-01.TR30




Date: 24.JUN.2021 19:59:14

BE-NR-LOW, MIMO-B, 802.11n20-HT8, Ch169




BE-NR-HIGH, MIMO-B, 802.11n20-HT8, Ch169




Date: 24.JUN.2021 20:02:22

BE-NR-LOW, MIMO-B, 802.11n20-HT8, Ch173




BE-NR-HIGH, MIMO-B, 802.11n20-HT8, Ch173




Date: 24.JUN.2021 20:01:28

BE-NR-LOW, MIMO-B, 802.11n20-HT8, Ch177




BE-NR-HIGH, MIMO-B, 802.11n20-HT8, Ch177




Date: 24 JUN 2021 20:02:35

BE-NR-LOW, MIMO-B, 802.11n40-HT8, Ch167



BE-NR-HIGH, MIMO-B, 802.11n40-HT8, Ch167




Date: 24 JUN 2021 20:47:23

BE-NR-LOW, MIMO-B, 802.11n40-HT8, Ch175




BE-NR-HIGH, MIMO-B, 802.11n40-HT8, Ch175




Date: 24 JUN 2021 21:48:44

BE-NR-LOW, MIMO-B, 802.11ac80-VHT0, Ch171




BE-NR-HIGH, MIMO-B, 802.11ac80-VHT0, Ch171

Test Report N° 210209-01.TR30




Date: 24.JUN.2021 21:54:55

BE-NR-LOW, MIMO-B, 802.11ac160-VHT0, Ch163




BE-NR-HIGH, MIMO-B, 802.11ac160-VHT0, Ch163




Date: 24.JUN.2021 20:07:04

BE-NR-LOW, MIMO-B, 802.11ax20-MCS0, Ch169




BE-NR-HIGH, MIMO-B, 802.11ax20-MCS0, Ch169




Date: 24.JUN.2021 20:08:11

BE-NR-LOW, MIMO-B, 802.11ax20-MCS0, Ch173



BE-NR-HIGH, MIMO-B, 802.11ax20-MCS0, Ch173




Date: 24.JUN.2021 20:03:18

BE-NR-LOW, MIMO-B, 802.11ax20-MCS0, Ch177




BE-NR-HIGH, MIMO-B, 802.11ax20-MCS0, Ch177




Date: 24.JUN.2021 20:10:25

BE-NR-LOW, MIMO-B, 802.11ax40-MCS0, Ch167




BE-NR-HIGH, MIMO-B, 802.11ax40-MCS0, Ch167



Date: 24.JUN.2021 20:11:32


BE-NR-LOW, MIMO-B, 802.11ax40-MCS0, Ch175



BE-NR-HIGH, MIMO-B, 802.11ax40-MCS0, Ch175




Test Report N° 210209-01.TR30




Date: 24.JUN.2021 21:57:48

BE-NR-LOW, MIMO-B, 802.11ax80-MCS0, Ch171




BE-NR-HIGH, MIMO-B, 802.11ax80-MCS0, Ch171



Date: 24.JUN.2021 22:03:26

BE-NR-LOW, MIMO-B, 802.11ax160-MCS0, Ch163



BE-NR-HIGH, MIMO-B, 802.11ax160-MCS0, Ch163