



34

1. The controller is only available for bundle sales, not for single parts sales.
2. There is a groove design for FCC ID label location to prevent users tear off FCC ID label.