



Intertek Testing Services

ETL SEMKO

Report No.: 0006835

Tested By: ITS, Report No.: 0006835

Scan Settings (1 Range)

-----|----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No. Start Stop Name

21 9k 30M EW0698

dBuV

80

70

60

50


40

30

20

10

0



PAGE 1

Ctrl No.: N/B



Intertek Testing Services

ETL SEMKO

Report No.: 0006835

Tested By:ITS, Report No.:0006835

Scan Settings (1 Range)

----- Frequencies -----			Receiver Settings -----					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV

0.49000	26.8	48.0
---------	------	------

* limit exceeded

Ctrl No.: N/A