



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

September 4, 2007

RE: ATCB005371

FCC ID: MVASP1690-001T

I have a few comments on this application. Depending on your responses, kindly understand there may be additional comments.

1. The designator on the PCB could not be seen clearly on the internal photos.
Please provide better internal photos which allow us to clearly see the symbol of capacitor and R on the PCB.
2. It is required to show mode name and company name on the Label.
Please provide a FCC label with model name and company name on it.

~ George Chen
~ <mailto:george@atcb.com>
~ Taiwan Mobile: +886 930600123
~ SKYPE: georgeshirley

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.