Re: Supersede request for FCC ID: MXF-9901100078; Granted on 10/18/2012

To Whom It May Concern:

We, the undersigned, hereby request to supersede the submitted exhibit "Label and Location, test report-15C and test report-15E" as indicted below. This supersede is required due to the miscommunication regarding the USB interface is used for power input only and does not have communication function. Thanks.

12 Matches found for FCC ID 'MXF-9901100078'

View Attachment	Exhibit Type	Date Submitted to FCC	Display Type	Date Available
Attestation - General Declaration	Attestation Statements	10/18/2012	pdf	10/18/2012
Confidentiality Request	Cover Letter(s)	10/18/2012	pdf	10/18/2012
Cover Letter - Agent Authorization	Cover Letter(s)	10/18/2012	pdf	10/18/2012
External Photos	External Photos	10/18/2012	pdf	10/18/2012
Label and Location	ID Label/Location Info	10/18/2012	pdf	10/18/2012
<u>Internal Photos</u>	Internal Photos	10/18/2012	pdf	10/18/2012
Operational Description	Operational Description	10/18/2012	pdf	10/18/2012
RF Exposure Info	RF Exposure Info	10/18/2012	pdf	10/18/2012
Test Report - 15C	Test Report	10/18/2012	pdf	10/18/2012
Test Report - 15E	Test Report	10/18/2012	pdf	10/18/2012
Test Setup Photos	Test Setup Photos	10/18/2012	pdf	10/18/2012
User Manual	Users Manual	10/18/2012	pdf	10/18/2012

Sincerely yours,

Ellis Wu

Senior Manager

Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch

Phone: 886 3 318 3232 Fax: 886 3 327 0892

ellis.wu@tw.bureauveritas.com