


Appendix A. Test Photos

Radiated Emissions from 30 MHz to 1GHz



Radiated Emissions from 30 MHz to 1GHz



SPORTON INTERNATIONAL INC.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. Report Version : 57 of 60 : Rev. 01

Report No.: FR0O0612

FCC ID MXF-XWH1RX



Radiated Emissions from 1 GHz to 18GHz



Radiated Emissions from 1 GHz to 18GHz



SPORTON INTERNATIONAL INC.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. Report Version : 58 of 60 : Rev. 01

Report No.: FR0O0612


FCC ID MXF-XWH1RX



AC Power Conducted



AC Power Conducted



SPORTON INTERNATIONAL INC.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. Report Version : 59 of 60 : Rev. 01

Report No.: FR0O0612

FCC ID MXF-XWH1RX