Report Number: 3115850ATL-004 Issued: 02/26/2007

6.0 RF Output Power (Conducted) (FCC Part 2.1046 Cond)

Method:

Connect the transmitter output to a calibrated coaxial attenuator. Connect the other end of the attenuator to a power meter. Transmitter output was read off the power meter in dBm.

Performed the test at three frequencies (low, middle, and high channels) and on the highest power levels, which can be setup on the transmitter.

Canada typically requires this test to be repeated at +60° C and at -30° C.

Test Equipment Used:

Description:	Manufacturer:	Model:	Asset Number:	Cal Date:	Cal Due:
Attenuator, 10 dB, 50 Watt, DC-18GHz	Weinschel	47-10-34	200061	07/18/2006	07/18/2007
Cable E05 (Formerly HS 1500 N-N)	Huber-Suhner	Sucoflex 104PEA	E05	05/11/2006	05/11/2007
EMI Receiver	Hewlett Packard	8546A	211388	08/04/2006	08/04/2007
EMI Receiver, Preselector section	Hewlett Packard	85460A	211389	08/04/2006	08/04/2007

Results: The sample tested was found to Comply.


Photo:



Report Number: 3115850ATL-004 Issued: 02/26/2007

9.0 Field strength of spurious radiation (FCC Part 2.1053)

Photo:



Test set up rear

Plot: