

TELEFIELD

TELEFIELD LTD.

Flat D, 2/F., Vallant Industrial Centre,
2-12 Au Pui Wan Street, Fo Tan, N.T., H.K.
Tel.: +852 2605-2811 Fax: +852 3007-8968

Date: 11 Jan, 2011

To whom it may concern,

Declarations

FCC ID: MZV2-5255C/ IC:3921A-25255C (Base unit' ID)

I, the undersigned, hereby declare that

1. The device does not use the provisions of 47CFR 15.323 (c) (6), random waiting mechanism is not used in this system.
2. The provisions of 47CFR 15.323 (c) (10) and 47CFR 15.323 (c) (11) are not used to extend the range of spectrum occupied over space or time for the purpose of denying fair access to spectrum to other devices.
3. Both base and handset units will act as the initiating devices, which will initiate the establishment of the duplex connection.
4. The device complies with the provisions of 47CFR 15.319(f). The device shall automatically discontinue transmission in case of either absence of information to transmit or operational failure. These provisions are not intended to preclude transmission of control and signaling information or use of repetitive codes used by certain digital technologies to complete frame or burst intervals. The following table explains the reaction of device in case of either absence of information to transmit or operational failure after a connection of its companion device is established.

	Circumstances	Reaction of Base Unit	Reaction of Handset
1	Switch-off device	NA	NA
2	Remove power from device	A	C
3	On Hook on device side	B	C
4	Switch-off companion device	NA	NA
5	Remove power from companion device	B	A
6	On Hook by companion device	B	C

- A - Connection is terminated and, transmission ceases.
B - Connection is terminated but device transmits control or signalling information.
C - Connection is terminated but companion device transmits control or signalling information.
N - Not applicable

If you have questions or need further information, please contact the undersigned.

Regards,
For and on behalf of
TELEFIELD LTD.

.....
Authorized Signature(s)
HO Wing Cheong
Senior Engineer Manager