



TELEFIELD LTD.

Flat D, 2/F., Valiant Industrial Centre,  
2-12 Au Pui Wan Street, Fo Tan, N.T., H.K.  
Tel.: +852 2605-2811 Fax: +852 3007-8968

\*\*\*\*\*

Nov 26<sup>th</sup>, 2010  
To whom it may concern,

Label Location Justification

FCC ID: MZV2-5255C, MZV2-5270B

Request is hereby submitted by Telefield Ltd. to request an alternative method of positively identifying the equipment, pursuant to 47 CFR § 2.925(f) of the FCC Rules.

The FCC identifier for handset will be placed in the battery compartment and the following requirements are confirmed to meet:


- a) The FCC identifier will visible at the time of purchase, by either of the following approaches:
  - Marketing the device without the battery installed, or
  - Providing instruction (stated on the box, user manual, or additional documentation) directing the user as to where to find the FCC label.
- b) The user accessible area will not require any special tools for access and the FCC label will not be placed on a removable part.

The user manual has already included the FCC statements, pursuant to 47 CFR § 15.19(a)(3), 15.21 and 15.105(b).

If you have questions or need further information, please contact the undersigned.

Sincerely,

or and on behalf of  
TELEFIELD LTD.

  
.....  
Ho Wing Cheong

Senior Engineering Manager