


RE: CP8331 UNIT BOTTOM



CAUTION : ALWAYS DISCONNECT ALL TELEPHONE LINES AND ELECTRICAL SUPPLIES FROM THE WALL OUTLETS BEFORE SERVICING OR DISASSEMBLING THIS EQUIPMENT OR REPLACING THE BATTERIES.

TELEFIELD LTD.

MODEL NO.
CP8331
HAC

FCC ID: MZVCP8331BR POWER: 9 V AC, 50/60 Hz, 0.2 AMPS
This equipment complies with FCC Rules, Part 68

FCC Registration Number:
Ringer Equivalence: 0.2B

Privacy of communications may not be ensured when using this phone.

Uses Jack: USOC RJ11C

Manufactured: **TF0001**

Serial No.: **C0575168**


TELEPHONE EQUIPMENT

CE mark with "US" and "72570"


Made in China

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:
1. This device may not cause harmful interference, and
2. This device must accept any interference received, including interference that may cause undesired operation.

RE: CP8331 FCC ID LABEL LOCATION ON
HANDSET BOTTOM VIEW



1:1



2:1