



11/04/2011

To whom it may concern,

**Label Location Justification**

**FCC ID: MZVTFY7446C**

Request is hereby submitted by **Telefield Limited** to request an alternative method of positively identifying the equipment, pursuant to 47 CFR § 2.925(f) of the FCC Rules.

The FCC identifier for baby unit of models: Y7443C, Y7444C, Y7445C and Y7446C will be placed in the battery compartment and the following requirements are confirmed to meet:

- a) The FCC identifier will be visible at the time of purchase, by either of the following approaches:
  - Marketing the device without the battery installed, or
  - Providing instruction (stated on the box, user manual, or additional documentation) directing the user as to where to find the FCC label.
- b) The user accessible area will not require any special tools for access and the FCC label will not be placed on a removable part.

The user manual has already included the FCC statements, pursuant to 47 CFR § 15.19(a)(3), 15.21 and 15.105(b).

If you have questions or need further information, please contact the undersigned.

Sincerely,

  
\_\_\_\_\_  
Wing Cheng Ho  
Engineering Manager