

Correspondence by Project

Project Number:

1335925136

Correspondence Number	Memo
N2S-SC3500-1	<p>1) The sample FCC ID label does not include the required statement from section 15.19 of the FCC rules. Please provide a corrected FCC ID label. Response: Please see the revised exhibit that shows the new labels with the FCC statement from section 15.19</p> <p>2) Please provide a new letter of appointment and Anti-drug abuse letter that is addressed to CETCB. Response: The letter has been uploaded.</p> <p>3) Please provide data and calculations showing compliance to the MPE requirements. Response: The MPE Calculations have been uploaded</p> <p>4) Please provide data showing compliance to the power variation requirements in section 15.31(e) of the FCC rules. Response: The 15.31 (e) Requirements have been uploaded.</p> <p>5) Please provide information regarding the antennas used. Response: The antenna data sheet has been uploaded.</p> <p>6) The photos of the device show a standard TNC connector being used, however this does not meet the requirements of section 15.203 which requires use of a unique connector. Please provide documentation showing compliance to the section 15.203 requirements. Response: The cover letter showing the requirements to this have been uploaded.</p> <p>7) The operational description describes an additional four operational bandwidths that can be used, however only one was tested. Please provide data showing compliance to the other operational bandwidths. Response: The Operational Description has been revised and uploaded.</p> <p>8) The user manual describes additional operational bandwidths and power levels that can be selected, however some of these were not tested or a above the allowed limits. Please provide a corrected user manual. Response: The Manual has been revised and uploaded.</p>