

MODEL NO: ADX-R-78P

Tested To Comply with FCC Standards

FCC ID: N52-ADX-R-78P For In-Building Application

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:
(1) This device may not cause harmful interference, and (2) this device must accept any interference receivde,

including interference that may cause undesired operation.



Product : Repeater

Input: 100-130/210-240V~, 50/60Hz, 13/7.5A

SEE INSTALLATION INSTRUCTIONS BEFORE CONNECTING TO THE SUPPLY

Advanced RF Technologies 3116 WEST VANOWEN ST, BURBANK, CA91505

S/N: ADXR7830M153006



Part 90 Signal Boosters

THIS IS A 90.219 CLASS B DEVICE

WARNING. THIS is NOT a CONSUMER device. It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC Licensee to operate this device. You MUST register Class B siginal booster (as defined in 47 CFR 90.219) online at www.fcc.gov/signal-boosters/registration. Unauthorized use may result in significant forfeiture penalties, including penalties in excess \$100,000 for each continuing violation.