

APPENDIX 3: Photographs of test setup

Conducted Emission
(External Antenna)




Photo 1




Photo 2

Conducted Emission
(Internal Antenna)




Photo 1




Photo 2

UL Japan, Inc.
Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Radiated Spurious Emission
(External Antenna)




Photo 1




Photo 2

Radiated Spurious Emission
(Internal Antenna)



Photo 1




Photo 2


UL Japan, Inc.
Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN
Telephone : +81 596 24 8999
Facsimile : +81 596 24 8124


Worst Case Position
(External Antenna)

Antenna (Horizontal: Z-axis/ Vertical:Y-axis)
Module (Horizontal: X-axis/ Vertical:X-axis)

X-axis




X-axis



Y-axis




Y-axis



Z-axis



Z-axis




Worst Case Position
(Internal Antenna)
Above 1GHz (Horizontal: Z-axis/ Vertical: Y-axis)

X-axis



Y-axis



Z-axis



End of Report