



Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch  
No. 19, Hwa Ya 2nd Rd., Wen Hwa Tsuen, Kwei Shan Hsiang, Taoyuan Hsien 33383, Taiwan

A D T TEL: 886-3-3183232 FAX: 886-3-3270892

Date: September 20, 2016

## RSE Justification Letter

Dear Examiner,

We, Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch., declare that the device without RSE testing due to the following:

- The end product (**Brand: Dell, Model: T04E**) with module under **FCC ID: N7NEM7355-D7** was assessed compliant to radiated emission limits per FCC requests in its initial FCC approval.
- Original FCC testing was performing with higher gain of antenna. The end product under this application uses antenna with lower gain across the emission bands. Hence it is apparent that the current platform yields lower level of radiated emission. And the ERP/EIRP is observed per FCC requests.
- The original FCC testing on module under **FCC ID: N7NEM7355-D7** was performed when the antenna was connected to the module in an open environment. The current platform under application has the antenna installed inside the laptop enclosure. The physical restraints introduced by laptop enclosure should have resulted in equal or lower level of radiated emission.

Should you have any question or comment regarding this matter, please have my best attention.

Sincerely yours,

Daniel Lee / Vice President

Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch

Tel: 886 3 318 3232

Fax: 886 3 327 0892

E-mail: [daniel-ch.lee@tw.bureauveritas.com](mailto:daniel-ch.lee@tw.bureauveritas.com)