FCC ID: N7NVOQA11

### **Radiated Emissions**


### Worst Orientation when the receiving antenna is vertical, (Y orientation)



 $EUT: Tri-band \ (850/1800/1900MHz) \ Voq \ Professional \ Phone$ 

FCC ID: N7NVOQA11

#### Worst Orientation when the receiving antenna is horizontal, (Z orientation)



 $EUT: \ Tri-band\ (850/1800/1900MHz)\ Voq\ Professional\ Phone$ 

FCC ID: N7NVOQA11

## **Radiated Emission photos**

### **Front view**



REPORT NO: 03U2438-1 DATE: JANUARY 14, 2004

 $EUT: \ Tri-band\ (850/1800/1900MHz)\ Voq\ Professional\ Phone$ 

FCC ID: N7NVOQA11

### **Back view**




REPORT NO: 03U2438-1 DATE: JANUARY 14, 2004

 $EUT:\ Tri-band\ (850/1800/1900MHz)\ Voq\ Professional\ Phone$ 

FCC ID: N7NVOQA11

# **LINE CONDUCTION - FRONT**



Page 32 of 34

REPORT NO: 03U2438-1 DATE: JANUARY 14, 2004

 $EUT: \ Tri-band\ (850/1800/1900MHz)\ Voq\ Professional\ Phone$ 

FCC ID: N7NVOQA11

#### **LINE CONDUCTION - BACK**



Page 33 of 34