



B12_CH23035_5M_16-QAM_1RB0_150k




Date: 19.NOV.2019 19:50:59

B12_CH23035_5M_16-QAM_1RB0_15k




Date: 13.NOV.2019 19:47:09

B12_CH23035_5M_16-QAM_25RB0_150k




Date: 19.NOV.2019 19:51:54

B12_CH23035_5M_16-QAM_25RB0_15k




Date: 13.NOV.2019 19:47:54

B12_CH23155_5M_16-QAM_1RB24_150k




Date: 13 NOV 2019 20:18:45

B12_CH23155_5M_16-QAM_1RB24_15k




Date: 13 NOV 2019 20:17:17

B12_CH23155_5M_16-QAM_25RB0_150k




Date: 13.NOV.2019 20:23:14

B12_CH23155_5M_16-QAM_25RB0_15k




Date: 13.NOV.2019 20:37:01

B12_CH23060_10M_QPSK_1RB0_150k




Date: 19.NOV.2019 19:54:40

B12_CH23060_10M_QPSK_1RB0_15k




Date: 13.NOV.2019 19:52:58

B12_CH23060_10M_QPSK_50RB0_150k




Date: 19.NOV.2019 19:52:45

B12_CH23060_10M_QPSK_50RB0_15k




Date: 13.NOV.2019 20:02:34

B12_CH23130_10M_QPSK_1RB49_150k




Date: 13 NOV 2019 20:09:38

12_CH23130_10M_QPSK_1RB49_15k




Date: 13 NOV 2019 20:10:28

B12_CH23130_10M_QPSK_50RB0_150k




Date: 13.NOV.2019 20:14:22

B12_CH23130_10M_QPSK_50RB0_15k




Date: 13.NOV.2019 20:13:51

B12_CH23060_10M_16-QAM_1RB0_150k




Date: 19.NOV.2019 19:54:04

B12_CH23060_10M_16-QAM_1RB0_15k




Date: 13.NOV.2019 19:54:32

B12_CH23060_10M_16-QAM_50RB0_150k




Date: 19.NOV.2019 19:53:28

B12_CH23060_10M_16-QAM_50RB0_15k




Date: 13.NOV.2019 19:58:49

B12_CH23130_10M_16-QAM_1RB49_150k




Date: 13 NOV 2019 20:11:55

B12_CH23130_10M_16-QAM_1RB49_15k




Date: 13 NOV 2019 20:11:08

B12_CH23130_10M_16-QAM_50RB0_150k



Date: 13.NOV.2019 20:12:43


B12_CH23130_10M_16-QAM_50RB0_15k



Date: 13.NOV.2019 20:13:15


Product	Module		
Test Item	Spurious Emissions at Antenna Terminals		
Test Mode	Mode 5: LTE Band 13		
Date of Test	2019/11/13	Test Site	SR10-H

B13_CH23205_5M_QPSK_1RB0_150k




Date: 13.NOV.2019 21:13:04

B13_CH23205_5M_QPSK_1RB0_15k




Date: 13.NOV.2019 21:14:09

B13_CH23205_5M_QPSK_25RB0_150k




Date: 13.NOV.2019 21:26:50

B13_CH23205_5M_QPSK_25RB0_15k




Date: 13.NOV.2019 21:26:12

B13_CH23255_5M__QPSK_1RB24_150k




Date: 13 NOV 2019 21:53:53

B13_CH23255_5M__QPSK_1RB24_15k




Date: 13 NOV 2019 21:55:42

LTE_B13_CH23255_5M__QPSK_25RB0_150k




Date: 13.NOV.2019 21:58:23

B13_CH23255_5M__QPSK_25RB0_15k




Date: 13.NOV.2019 21:59:21

B13_CH23205_5M_16-QAM_1RB0_150k



Date: 13 NOV 2019 21:19:42

B13_CH23205_5M_16-QAM_1RB0_15k




Date: 13 NOV 2019 21:17:55

B13_CH23205_5M_16-QAM_25RB0_150k




Date: 13.NOV.2019 21:23:40

B13_CH23205_5M_16-QAM_25RB0_15k




Date: 13.NOV.2019 21:24:18

B13_CH23255_5M_16-QAM_1RB24_150k



Date: 13 NOV 2019 21:57:47

B13_CH23255_5M_16-QAM_1RB24_15k




Date: 13 NOV 2019 21:56:36

B13_CH23255_5M_16-QAM_25RB0_150k




Date: 13.NOV.2019 22:00:58

B13_CH23255_5M_16-QAM_25RB0_15k




Date: 13.NOV.2019 22:00:12

B13_CH23230_10M_QPSK_1RB0_150k




Date: 13 NOV 2019 21:29:18

B13_CH23230_10M_QPSK_1RB0_15k




Date: 13 NOV 2019 21:30:29

B13_CH23230_10M__QPSK_50RB0_150k




Date: 13.NOV.2019 21:37:49

B13_CH23230_10M__QPSK_50RB0_15k




Date: 13.NOV.2019 21:36:43

B13_CH23230_10M_QPSK_1RB49_150k




Date: 13 NOV 2019 21:44:01

B13_CH23230_10M_QPSK_1RB49_15k




Date: 13 NOV 2019 21:44:39

B13_CH23230_10M_QPSK_50RB0_150k




Date: 13.NOV.2019 21:39:20

B13_CH23230_10M_QPSK_50RB0_15k




Date: 13.NOV.2019 21:40:30

B13_CH23230_10M_16-QAM__1RB0_150k



Date: 13 NOV 2019 21:31:40

B13_CH23230_10M_16-QAM__1RB0_15k




Date: 13 NOV 2019 21:31:05

B13_CH23230_10M_16-QAM__50RB0_150k




Date: 13.NOV.2019 21:32:21

B13_CH23230_10M_16-QAM__50RB0_15k




Date: 13.NOV.2019 21:32:55

B13_CH23230_10M_16-QAM_1RB49_150k




Date: 13 NOV 2019 21:47:04

B13_CH23230_10M_16-QAM_1RB49_15k




Date: 13 NOV 2019 21:46:45

B13_CH23230_10M_16-QAM_50RB0_150k



Date: 13.NOV.2019 21:41:57


B13_CH23230_10M_16-QAM_50RB0_15k



Date: 13.NOV.2019 21:41:12


Product	Module		
Test Item	Spurious Emissions at Antenna Terminals		
Test Mode	Mode 6: LTE Band 25		
Date of Test	2019/08/17	Test Site	SR10-H

LTE_B25_CH26047_1.4M_QPSK_1RB0




Date: 17.AUG.2019 01:45:01

LTE_B25_CH26047_1.4M_QPSK_6RB0




Date: 17.AUG.2019 01:46:38

LTE_B25_CH26047_1.4M_16-QAM_1RB0



Date: 17.AUG.2019 01:45:41

LTE_B25_CH26047_1.4M_16-QAM_6RB0




Date: 17.AUG.2019 01:47:21

LTE_B25_CH26683_1.4M_QPSK_1RB5




Date: 17.AUG.2019 01:49:26

LTE_B25_CH26683_1.4M_QPSK_6RB0




Date: 17.AUG.2019 01:48:24

LTE_B25_CH26683_1.4M_16-QAM_1RB5




Date: 17.AUG.2019 01:49:58

LTE_B25_CH26683_1.4M_16-QAM_6RB0




Date: 17.AUG.2019 01:48:00

LTE_B25_CH26055_3M_QPSK_1RB0




Date: 17.AUG.2019 01:44:07

LTE_B25_CH26055_3M_QPSK_15RB0




Date: 17.AUG.2019 01:42:26

LTE_B25_CH26055_3M_16-QAM_1RB0




Date: 17.AUG.2019 01:43:43

LTE_B25_CH26055_3M_16-QAM_15RB0




Date: 17.AUG.2019 01:43:05

LTE_B25_CH26365_3M_QPSK_1RB14




Date: 17.AUG.2019 01:39:03

LTE_B25_CH26365_3M_QPSK_15RB0




Date: 17.AUG.2019 01:41:36

LTE_B25_CH26365_3M_16-QAM_1RB14




Date: 17.AUG.2019 01:40:17

LTE_B25_CH26365_3M_16-QAM_15RB0




Date: 17.AUG.2019 01:41:18

LTE_B25_CH26065_5M_QPSK_1RB0




Date: 17.AUG 2019 01:34:30

LTE_B25_CH26065_5M_QPSK_25RB0




Date: 17.AUG 2019 01:36:13

LTE_B25_CH26065_5M_16-QAM_1RB0




Date: 17.AUG.2019 01:35:08

LTE_B25_CH26065_5M_16-QAM_25RB0




Date: 17.AUG.2019 01:35:46

LTE_B25_CH26665_5M_QPSK_1RB24




Date: 17.AUG.2019 01:38:06

LTE_B25_CH26665_5M_QPSK_25RB0




Date: 17.AUG.2019 01:36:43

LTE_B25_CH26665_5M_16-QAM_1RB24




Date: 17.AUG.2019 01:37:50

LTE_B25_CH26665_5M_16-QAM_25RB0




Date: 17.AUG.2019 01:37:16

LTE_B25_CH26090_10M_QPSK_1RB0




Date: 17.AUG.2019 01:33:37

LTE_B25_CH26090_10M_QPSK_50RB0




Date: 17.AUG.2019 01:32:23

LTE_B25_CH26090_10M_16-QAM_1RB0




Date: 17.AUG.2019 01:33:20

LTE_B25_CH26090_10M_16-QAM_50RB0




Date: 17.AUG.2019 01:32:49

LTE_B25_CH26640_10M_QPSK_1RB49




Date: 17.AUG.2019 01:28:53

LTE_B25_CH26640_10M_QPSK_50RB0




Date: 17.AUG.2019 01:31:43

LTE_B25_CH26640_10M_16-QAM_1RB49




Date: 17.AUG.2019 01:29:44

LTE_B25_CH26640_10M_16-QAM_50RB0




Date: 17.AUG.2019 01:30:30

LTE_B25_CH26115_15M_QPSK_1RB0




Date: 17.AUG.2019 01:23:35

LTE_B25_CH26115_15M_QPSK_75RB0




Date: 17.AUG.2019 01:25:00

LTE_B25_CH26115_15M_16-QAM_1RB0




Date: 17.AUG.2019 01:24:02

LTE_B25_CH26115_15M_16-QAM_75RB0




Date: 17.AUG.2019 01:24:41

LTE_B25_CH26615_15M_QPSK_1RB74




Date: 17.AUG.2019 01:27:38

LTE_B25_CH26615_15M_QPSK_75RB0




Date: 17.AUG.2019 01:25:42

LTE_B25_CH26615_15M_16-QAM_1RB74




Date: 17.AUG.2019 01:27:08

LTE_B25_CH26615_15M_16-QAM_75RB0




Date: 17.AUG.2019 01:26:10

LTE_B25_CH26140_20M_QPSK_1RB0




Date: 17.AUG.2019 01:16:02

LTE_B25_CH26140_20M_QPSK_100RB0




Date: 17.AUG.2019 01:19:47

LTE_B25_CH26140_20M_16-QAM_1RB0




Date: 17.AUG.2019 01:17:38

LTE_B25_CH26140_20M_16-QAM_100RB0




Date: 17.AUG.2019 01:19:17

LTE_B25_CH26590_20M_QPSK_1RB99




Date: 17.AUG.2019 01:22:32

LTE_B25_CH26590_20M_QPSK_100RB0




Date: 17.AUG.2019 01:20:27

LTE_B25_CH26590_20M_16-QAM_1RB99



Date: 17.AUG.2019 01:22:06


LTE_B25_CH26590_20M_16-QAM_100RB0



Date: 17.AUG.2019 01:21:19


Product	Module		
Test Item	Spurious Emissions at Antenna Terminals (Part 22)		
Test Mode	Mode 7: LTE Band 26		
Date of Test	2019/08/17~2019/08/20	Test Site	SR10-H

LTE_B26_CH26797_1.4M_QPSK_1RB0 (Part 22)




Date: 20 AUG. 2019 06:00:13

LTE_B26_CH26797_1.4M_QPSK_6RB0 (Part 22)




Date: 20 AUG. 2019 06:03:47

LTE_B26_CH26797_1.4M_16-QAM_1RB0 (Part 22)



Date: 20 AUG 2019 05:57:32

LTE_B26_CH26797_1.4M_16-QAM_6RB0 (Part 22)




Date: 20 AUG 2019 06:04:54

LTE_B26_CH27033_1.4M_QPSK_1RB5 (Part 22)



Date: 17.AUG.2019 02:23:28

LTE_B26_CH27033_1.4M_QPSK_6RB0 (Part 22)




Date: 17.AUG.2019 02:22:52

LTE_B26_CH27033_1.4M_16-QAM_1RB5 (Part 22)




Date: 17.AUG.2019 02:24:09

LTE_B26_CH27033_1.4M_16-QAM_6RB0 (Part 22)




Date: 17.AUG.2019 02:22:05

LTE_B26_CH26805_3M_QPSK_1RB0 (Part 22)




Date: 20 AUG 2019 06:50:25

LTE_B26_CH26805_3M_QPSK_15RB0 (Part 22)




Date: 20 AUG 2019 06:52:32

LTE_B26_CH26805_3M_16-QAM_1RB0 (Part 22)




Date: 20 AUG 2019 06:51:02

LTE_B26_CH26805_3M_16-QAM_15RB0 (Part 22)




Date: 20 AUG 2019 06:52:05

LTE_B26_CH27025_3M_QPSK_1RB14 (Part 22)




Date: 17.AUG.2019 02:36:54

LTE_B26_CH27025_3M_QPSK_15RB0 (Part 22)




Date: 17.AUG.2019 02:37:44

LTE_B26_CH27025_3M_16-QAM_1RB14 (Part 22)




Date: 17.AUG.2019 02:36:23

LTE_B26_CH27025_3M_16-QAM_15RB0 (Part 22)




Date: 17.AUG.2019 02:38:11

LTE_B26_CH26815_5M_QPSK_1RB0 (Part 22)




Date: 20 AUG 2019 06:57:06

LTE_B26_CH26815_5M_QPSK_25RB0 (Part 22)




Date: 20 AUG 2019 06:53:59

LTE_B26_CH26815_5M_16-QAM_1RB0 (Part 22)




Date: 20 AUG 2019 06:56:31

LTE_B26_CH26815_5M_16-QAM_25RB0 (Part 22)




Date: 20 AUG 2019 06:55:47

LTE_B26_CH27015_5M_QPSK_1RB24 (Part 22)




Date: 17.AUG.2019 02:46:38

LTE_B26_CH27015_5M_QPSK_25RB0 (Part 22)




Date: 17.AUG.2019 02:45:49

LTE_B26_CH27015_5M_16-QAM_1RB24 (Part 22)




Date: 17.AUG.2019 02:47:00

LTE_B26_CH27015_5M_16-QAM_25RB0 (Part 22)




Date: 17.AUG.2019 02:45:28

LTE_B26_CH26840_10M_QPSK_1RB0 (Part 22)




Date: 20 AUG 2019 06:58:04

LTE_B26_CH26840_10M_QPSK_50RB0 (Part 22)




Date: 20 AUG 2019 07:00:15

LTE_B26_CH26840_10M_16-QAM_1RB0 (Part 22)




Date: 20 AUG 2019 06:58:55

LTE_B26_CH26840_10M_16-QAM_50RB0 (Part 22)




Date: 20 AUG 2019 06:59:44

LTE_B26_CH26990_10M_QPSK_1RB49 (Part 22)




Date: 17.AUG.2019 02:50:55

LTE_B26_CH26990_10M_QPSK_50RB0 (Part 22)




Date: 17.AUG.2019 02:51:54

LTE_B26_CH26990_10M_16-QAM_1RB49 (Part 22)




Date: 17.AUG.2019 02:49:45

LTE_B26_CH26990_10M_16-QAM_50RB0 (Part 22)




Date: 17.AUG.2019 02:52:13

LTE_B26_CH26865_15M_QPSK_1RB0 (Part 22)




Date: 20 AUG 2019 07:05:40

LTE_B26_CH26865_15M_QPSK_75RB0 (Part 22)




Date: 20 AUG 2019 07:03:12

LTE_B26_CH26865_15M_16-QAM_1RB0 (Part 22)




Date: 20.AUG.2019 07:05:03

LTE_B26_CH26865_15M_16-QAM_75RB0 (Part 22)




Date: 20.AUG.2019 07:04:16

LTE_B26_CH26965_15M_QPSK_1RB74 (Part 22)




Date: 17.AUG.2019 02:59:37

LTE_B26_CH26965_15M_QPSK_75RB0 (Part 22)




Date: 17.AUG.2019 02:59:09

LTE_B26_CH26965_15M_16-QAM_1RB74 (Part 22)



Date: 17.AUG.2019 02:59:54


LTE_B26_CH26965_15M_16-QAM_75RB0 (Part 22)



Date: 17.AUG.2019 02:58:29


Product	Module		
Test Item	Spurious Emissions at Antenna Terminals (Part 90)		
Test Mode	Mode 7: LTE Band 26		
Date of Test	2019/08/19	Test Site	SR10-H

LTE_B26_CH26697_1.4M_QPSK_1RB0 (Part 90)




Date: 19 AUG 2019 10:33:29

LTE_B26_CH26697_1.4M_QPSK_6RB0 (Part 90)




Date: 19 AUG 2019 10:35:23

LTE_B26_CH26697_1.4M_16-QAM_1RB0 (Part 90)




Date: 19.AUG.2019 10:33:57

LTE_B26_CH26697_1.4M_16-QAM_6RB0 (Part 90)




Date: 19.AUG.2019 10:35:01

LTE_B26_CH26783_1.4M_QPSK_1RB5 (Part 90)




Date: 19 AUG 2019 10:40:14

LTE_B26_CH26783_1.4M_QPSK_6RB0 (Part 90)




Date: 19 AUG 2019 10:36:05

LTE_B26_CH26783_1.4M_16-QAM_1RB5 (Part 90)




Date: 19 AUG 2019 10:37:28

LTE_B26_CH26783_1.4M_16-QAM_6RB0 (Part 90)




Date: 19 AUG 2019 10:36:36

LTE_B26_CH26705_3M_QPSK_1RB14 (Part 90)




Date: 19 AUG 2019 10:49:46

LTE_B26_CH26705_3M_QPSK_15RB0 (Part 90)




Date: 19 AUG 2019 10:47:58

LTE_B26_CH26705_3M_16-QAM_1RB14 (Part 90)




Date: 19 AUG 2019 10:49:18

LTE_B26_CH26705_3M_16-QAM_15RB0 (Part 90)




Date: 19 AUG 2019 10:48:34

LTE_B26_CH26775_3M_QPSK_1RB14 (Part 90)




Date: 19 AUG 2019 10:40:51

LTE_B26_CH26775_3M_QPSK_15RB0 (Part 90)




Date: 19 AUG 2019 10:46:39

LTE_B26_CH26775_3M_16-QAM_1RB14 (Part 90)




Date: 19 AUG 2019 10:41:22

LTE_B26_CH26775_3M_16-QAM_15RB0 (Part 90)




Date: 19 AUG 2019 10:46:59

LTE_B26_CH26715_5M_QPSK_1RB0 (Part 90)




Date: 19 AUG 2019 11:43:40

LTE_B26_CH26715_5M_QPSK_25RB0 (Part 90)




Date: 19 AUG 2019 11:46:29

LTE_B26_CH26715_5M_16-QAM_1RB0 (Part 90)




Date: 19.AUG.2019 11:44:05

LTE_B26_CH26715_5M_16-QAM_25RB0 (Part 90)




Date: 19.AUG.2019 11:46:15

LTE_B26_CH26765_5M_QPSK_1RB24 (Part 90)




Date: 19 AUG 2019 10:42:44

LTE_B26_CH26765_5M_QPSK_25RB0 (Part 90)




Date: 19 AUG 2019 10:44:05

LTE_B26_CH26765_5M_16-QAM_1RB24 (Part 90)




Date: 19.AUG.2019 10:42:19

LTE_B26_CH26765_5M_16-QAM_25RB0 (Part 90)




Date: 19.AUG.2019 10:44:54

LTE_B26_CH26740_10M_QPSK_1RB0 (Part 90)




Date: 19 AUG 2019 10:19:19

LTE_B26_CH26740_10M_QPSK_1RB49 (Part 90)




Date: 19 AUG 2019 10:22:35

LTE_B26_CH26740_10M_QPSK_50RB0 (Part 90)



Date: 19 AUG 2019 10:23:13

LTE_B26_CH26740_10M_16-QAM_1RB0 (Part 90)




Date: 19 AUG 2019 10:21:18

LTE_B26_CH26740_10M_16-QAM_1RB49 (Part 90)



Date: 19 AUG 2019 10:22:03


LTE_B26_CH26740_10M_16-QAM_50RB0 (Part 90)



Date: 19 AUG 2019 10:23:38


Product	Module		
Test Item	Spurious Emissions at Antenna Terminals		
Test Mode	Mode 8: LTE Band 66		
Date of Test	2019/08/19	Test Site	SR10-H

LTE_B66_CH131979_1.4M_QPSK_1RB0




Date: 19 AUG 2019 12:10:49

LTE_B66_CH131979_1.4M_QPSK_6RB0




Date: 19 AUG 2019 13:26:42

LTE_B66_CH131979_1.4M_16-QAM_1RB0




Date: 19.AUG.2019 12:11:33

LTE_B66_CH131979_1.4M_16-QAM_6RB0




Date: 19.AUG.2019 13:26:23

LTE_B66_CH132665_1.4M_QPSK_1RB5




Date: 19 AUG 2019 13:48:52

LTE_B66_CH132665_1.4M_QPSK_6RB0




Date: 19 AUG 2019 13:35:44

LTE_B66_CH132665_1.4M_16-QAM_1RB5




Date: 19.AUG.2019 13:48:21

LTE_B66_CH132665_1.4M_16-QAM_6RB0




Date: 19.AUG.2019 13:36:09

LTE_B66_CH131987_3M_QPSK_1RB0




Date: 19.AUG.2019 14:17:56

LTE_B66_CH131987_3M_QPSK_15RB0




Date: 19.AUG.2019 14:15:12

LTE_B66_CH131987_3M_16-QAM_1RB0




Date: 19.AUG.2019 14:17:32

LTE_B66_CH131987_3M_16-QAM_15RB0




Date: 19.AUG.2019 14:16:56

LTE_B66_CH132657_3M_QPSK_1RB14




Date: 19 AUG 2019 14:06:00

LTE_B66_CH132657_3M_QPSK_15RB0




Date: 19 AUG 2019 14:13:02

LTE_B66_CH132657_3M_16-QAM_1RB14




Date: 19.AUG.2019 14:06:28

LTE_B66_CH132657_3M_16-QAM_15RB0




Date: 19.AUG.2019 14:12:34

LTE_B66_CH131997_5M_QPSK_1RB0




Date: 19 AUG 2019 14:50:04

LTE_B66_CH131997_5M_QPSK_25RB0




Date: 19 AUG 2019 15:01:55

LTE_B66_CH131997_5M_16-QAM_1RB0




Date: 19.AUG.2019 14:50:37

LTE_B66_CH131997_5M_16-QAM_25RB0




Date: 19.AUG.2019 15:00:56

LTE_B66_CH132647_5M_QPSK_1RB24




Date: 19 AUG 2019 15:15:39

LTE_B66_CH132647_5M_QPSK_25RB0




Date: 19 AUG 2019 15:02:29

LTE_B66_CH132647_5M_16-QAM_1RB24




Date: 19.AUG.2019 15:15:18

LTE_B66_CH132647_5M_16-QAM_25RB0




Date: 19.AUG.2019 15:03:56

LTE_B66_CH132022_10M_QPSK_1RB0




Date: 19 AUG 2019 16:08:32

LTE_B66_CH132022_10M_QPSK_50RB0




Date: 19 AUG 2019 16:05:40

LTE_B66_CH132022_10M_16-QAM_1RB0




Date: 19.AUG.2019 16:08:07

LTE_B66_CH132022_10M_16-QAM_50RB0




Date: 19.AUG.2019 16:07:40

LTE_B66_CH132622_10M_QPSK_1RB49




Date: 19 AUG 2019 15:47:03

LTE_B66_CH132622_10M_QPSK_50RB0




Date: 19 AUG 2019 15:51:46

LTE_B66_CH132622_10M_16-QAM_1RB49




Date: 19.AUG.2019 15:47:43

LTE_B66_CH132622_10M_16-QAM_50RB0




Date: 19.AUG.2019 15:51:19

LTE_B66_CH132047_15M_QPSK_1RB0




Date: 19 AUG 2019 16:17:48

LTE_B66_CH132047_15M_QPSK_75RB0




Date: 19 AUG 2019 16:22:22

LTE_B66_CH132047_15M_16-QAM_1RB0




Date: 19.AUG.2019 16:19:28

LTE_B66_CH132047_15M_16-QAM_75RB0




Date: 19.AUG.2019 16:21:57

LTE_B66_CH132597_15M_QPSK_1RB74




Date: 19 AUG 2019 16:42:09

LTE_B66_CH132597_15M_QPSK_75RB0




Date: 19 AUG 2019 16:38:21

LTE_B66_CH132597_15M_16-QAM_1RB74




Date: 19.AUG.2019 16:41:45

LTE_B66_CH132597_15M_16-QAM_75RB0




Date: 19.AUG.2019 16:39:06

LTE_B66_CH132072_20M_QPSK_1RB0




Date: 19 AUG 2019 17:02:42

LTE_B66_CH132072_20M_QPSK_100RB0




Date: 19 AUG 2019 17:00:32

LTE_B66_CH132072_20M_16-QAM_1RB0



Date: 19.AUG.2019 17:02:24

LTE_B66_CH132072_20M_16-QAM_100RB0



Date: 19.AUG.2019 17:01:53