


S/N :
 MODEL: MD450
 TANAPA: HCUE1072A
 FCC ID: NC8MD450
 IC: 1945A-MD45X
 MADE IN CHINA

CAUTION:
 TO REDUCE RISK OF FIRE OR
 INJURY USE ONLY BATTERY
 TYPE INCLUDED.

ATTENTION:
 POUR RÉDUIRE LES RISQUES
 D'INCENDIE OU DE BLESSURE,
 UTILISEZ UNIQUEMENT LE MÊME
 TYPE DE PILE QUE CELLE INCLUSE.



This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation. Privacy of communications may not be ensured when using this phone. Complies with 47 CFR Part 68 requirements.

Reg. No.: US: 5GGW100BMD450
 USOC: RJ1C REN : 0.0B
 FCC ID: NC8MD450
 IC: 1945A-MD45X
 TNP: HCUE1074A
 MADE IN CHINA

HAC

 LISTED I.T.E.
 66CF
 E204488

 **MOTOROLA**

Model: MD450 S/N:

CAUTION: Please disconnect the power and phone cords before opening the battery door.