



TELEFAX MESSAGE

March 2, 1999

Mr. Joe Dichoso
FEDERAL COMMUNICATIONS COMMISSION
Columbia, MD

FAX #: 301/344-2050

REF #: 6310 (Pagerola)

I am sending to you explanations concerning the 3 problems you indicated on our Application for Certification of a FRS transceiver.

1. The antenna is not removable from outside this transceiver. It must be disassembled and an internal screw removed
2. Please certify the FRS unit at the ERP as you calculate it.
3. I have also included our frequency stability chart which shows that we tested at an ambient temperature of +20°C, -30°C and +50°C. We apologize for putting the negative sign (-) after the numeral (30).

If additional information is required please let me know.

Regards,

Communications for People Going Places
1544 Sawdust Rd. Ste. 303 The Woodlands, TX 77380
281-298-2029 FAX: 281-298-2863 www.gocomm.com gocomm@gocomm.com